Sellafield Ltd

Sellafield Site
Sellafield, Seascale
Cumbria, CA20 1PG
Tel: [redacted]

Your Reference:
2021/0033110
Response to Unique
Number: ONR-EL-21-001

28/05/2021

Dear [redacted]

Subject: Sellafield Ltd – Compliance with Scaffolding standards

I am writing to you in response to the letter referenced as [redacted]. Within that letter there were two actions identified, below is the evidence to support Sellafield Ltd close out of the actions.

1. Sellafield Ltd ensures that the scaffolding steps at the [redacted] Welfare Dome, where (name removed) injury occurred, are made safe and provides evidence to ONR that this work has been completed.

- Attached as appendix 1 are photos of the steps in their current status
- Attached as appendix 2 is the approved design and calculations used to install the updated platform.
- Prior to alteration the steps remained out of service.
- The steps and domes were returned to service on 15th May 2021, following independent assessment.

2. Sellafield Ltd confirms that similar scaffolding steps erected by Enigma Industrial Services Limited across site are compliant with the standards above and provides evidence to ONR that this work has been completed.

- As result of the identified shortfall an extent of condition was raised on the ATLAS system "BN2104A1492-Extent of Condition from Incident Occurred at [redacted] Welfare Dome Stairs"
- The following actions were raised on 29 areas across operations & projects at Sellafield.
  i. Carry out a review of all scaffold companies used in your area and identify any scaffold structures erected by Enigma and populate the attached spreadsheet.
  ii. Arrange for independent inspection of those structures identified in the spreadsheet, detail any shortfalls, rectifications required and completion of rectification. Installer to rectify. Spreadsheet to be uploaded to ATLAS for close out of action.
- All 58 ATLAS actions were completed and closed out by 26th April 2021
- The findings from these actions identified some remedial work or improvement action in PFCS, BEPPS/DIF, Sitewide Services & Estates.
- There is a spreadsheet available attached to the ATLAS close out that identifies all close out detail. Please advise if a copy of the full detail is required but to confirm the remedial work has all been completed.

I hope this meets with your expectations. Please contact me if you require any further information or clarity.

Regards,

[redacted]

[redacted]
Infrastructure

[redacted]

Appendix 1 – Photos (Word document)
Appendix 2 – 20-NWIND-047-.01 02F (drawing) & 20-NWIND-047-01-02F (Calculations) (PDF's)