

*Energy Act 2013 ("2013 Act"), Schedule 8, paragraphs 3, 5 and 6
Health and Safety at Work etc Act 1974, Sections 21, 23 and 24*

Serial Number **ONR-IN-23-004**

Schedule

In order to comply with this Notice you should:

- (1) Undertake any required examination, inspection, maintenance or testing so as to ensure that:
 - a. the manufacturer/supplier's advice in relation to changing the tail spindle thread pitch is appropriately considered and, where necessary, implemented, on any valves of the same or similar design to the 1C/SS/8 valve that failed on 23 December 2023;
 - b. the said valves are of the correct material and other design specifications as needed to ensure safety;
 - c. there are no other significant defects of concern associated with the said valves.
- (2) Ensure that any other information, advice or recommendations from the manufacturer/supplier is properly considered and, where necessary, implemented in relation to the said valves.

OR

Any other equally effective means of remedying the said contraventions.