



Office for Nuclear Regulation (ONR) Quarterly Site Report for Hinkley Point A nuclear licensed site

Report for period 1 July – 30 September 2015

Foreword

This report is issued as part of ONR's commitment to make information about inspection and regulatory activities relating to the above site available to the public. Reports are distributed quarterly to members for the Hinkley Point Site Stakeholder Group and are also available on the ONR website (<http://www.onr.org.uk/llc/>).

Site inspectors from ONR usually attend the Hinkley Point Site Stakeholder Group meetings and will respond to any questions raised there. Any person wishing to inquire about matters covered by this report should contact ONR.

TABLE OF CONTENTS

| | | |
|---|---------------------------|---|
| 1 | INSPECTIONS | 3 |
| 2 | ROUTINE MATTERS | 3 |
| 3 | NON-ROUTINE MATTERS | 3 |
| 4 | REGULATORY ACTIVITY | 4 |
| 5 | NEWS FROM ONR | 4 |
| 6 | CONTACTS | 4 |

1 INSPECTIONS

1.1 Dates of inspection

The ONR site inspector made inspections on the following dates during the quarter:

- 3-6 August 2015

2 ROUTINE MATTERS

2.1 Inspections

Inspections are undertaken as part of the process for monitoring compliance with:

- The conditions attached by ONR to the nuclear site licence granted under the Nuclear Installations Act 1965 (NIA65) (as amended);
- The Energy Act 2013;
- The Health and Safety at Work Act 1974 (HSWA74); and
- Regulations made under HSWA74, for example the Ionising Radiations Regulations 1999 (IRR99) and the Management of Health and Safety at Work Regulations 1999 (MHSWR99).

The inspections entail monitoring licensee's actions on the site in relation to incidents, operations, maintenance, projects, modifications, safety case changes and any other matters that may affect safety. The licensee is required to make and implement adequate arrangements under the conditions attached to the licence in order to ensure legal compliance. Inspections seek to judge both the adequacy of these arrangements and their implementation.

In this period, routine inspections of Berkeley covered the following:

- Site plans, designs and specifications;
- Modifications on existing plan;
- Decommissioning plans;
- Control and supervision of operations;
- Proposed changes to the site's organisational capability.

In general, ONR judged the arrangements made and implemented by the site in response to safety requirements to be adequate in the areas inspected. However, where improvements were considered necessary, the licensee made satisfactory commitments to address the issues, and the site inspector will monitor progress during future visits. Where necessary, ONR will take formal regulatory enforcement action to ensure that appropriate remedial measures are implemented to reasonably practicable timescales.

2.2 Other work

The site inspector held a periodic meeting with safety representatives, to support their function of representing employees and receiving information on matters affecting their health, safety and welfare at work.

3 NON-ROUTINE MATTERS

Licensees are required to have arrangements to respond to non-routine matters and events. ONR inspectors judge the adequacy of the licensee's response, including actions taken to implement any necessary improvements.

Matters and events that have been reported to ONR during this period are considered to be minor:

- Shift staffing levels on an occasion fell below the safety case requirements for a short period of time.
- Emergency pager tests failed in two instances, but sufficient people were contactable.
- The accidental fracture of a demineralised water pipe in an area where radioactive waste was present. The water did not become contaminated.

These matters and events have been dealt with in accordance with the licensee's arrangements, which ONR deems to be adequate. ONR is satisfied that the licensee has taken appropriate actions to implement improvements.

4 REGULATORY ACTIVITY

ONR may issue formal documents to ensure compliance with regulatory requirements. Under nuclear site licence conditions, ONR issues regulatory documents, which either permit an activity or require some form of action to be taken; these are usually collectively termed 'Licence Instruments' (LIs), but can take other forms. In addition, inspectors may issue Enforcement Notices to secure improvements to safety.

- No LIs or Enforcement Notices were issued during the period.

5 NEWS FROM ONR

Retirement of the Chief Nuclear Inspector

Dr Andy Hall, the first Chief Nuclear Inspector to hold this statutory office, announced his decision to retire from ONR in November 2015 and until his retirement he is taking a period of compassionate leave for personal reasons. The ONR Board, with the approval of the Secretary of State, has appointed Dr Richard Savage as Acting Chief Nuclear Inspector, pending a process to fill the role on a permanent basis. Richard was previously Head of the Defence Nuclear Safety Regulator before joining ONR in his current role as a Deputy Chief Nuclear Inspector.

Regulation Matters magazine

Insight into ONR's work as an independent regulator of the nuclear industry can be found in Regulation Matters. This quarterly online publication (<http://www.onr.org.uk/regulation-matters.htm>) reports on the key themes and developments in each of ONR's regulatory programmes and provides an update about the on-going changes at ONR. For the latest news and updates from ONR, you can also visit the website and sign up for our e-bulletin: <http://www.onr.org.uk/index.htm>.

CONTACTS

Office for Nuclear Regulation
Redgrave Court
Merton Road
Bootle
Merseyside
L20 7HS

website: www.onr.org.uk
email: ONREnquiries@onr.gsi.gov.uk

This document is issued by the Office for Nuclear Regulation (ONR). For further information about ONR, or to report inconsistencies or inaccuracies in this publication please visit <http://www.onr.org.uk/feedback.htm>.

© Office for Nuclear Regulation, 2015

If you wish to reuse this information visit www.onr.org.uk/copyright.htm for details.

Published 10/15

For published documents, the electronic copy on the ONR website remains the most current publicly available version and copying or printing renders this document uncontrolled.